

NEW ZEALAND TEMPORARY AND PRELIMINARY NOTICES IN FORCE
(NZ NTM Edition No. 19 dated 15 September 2017)

| NZ Notice | T/P | Charts Affected | Locality and Subject |
|-----------|-----|---|--|
| | | NZ Chart, ENC Cell | |
| 41/14 | P | NZ 268 | Chatham Islands: Depths and Rocks |
| 155/16 | P | NZ 4212 | West Coast, Hokianga Harbour: Uncharted depths and rocks |
| 159/16 | T | NZ 4424, NZ404424 | West Coast, Taharoa Offshore Terminal: Buoy |
| 182/16 | P | NZ 268 | Chatham Islands: Area of Restricted Access |
| 264/16 | T | NZ 4314, NZ404314 | West Coast, Manukau Harbour Entrance: Depths |
| 267/16 | T | NZ 561, NZ 5612, NZ400561, NZ505612, NZ605612 | East Coast, Hawke Bay, Napier Roads: Buoy and AIS |
| 44/17 | P | NZ 268, NZ 2683, NZ 2685, NZ402683, NZ526852 | Chatham Islands, Port Waitangi Wharf: Works |
| 49/17 | T | NZ 532, NZ 5321, NZ 5324, NZ305321, NZ305322, NZ405321, NZ405324 | East Coast, Tamaki Strait: Light Characteristics |
| 74/17 | P | NZ 5412 | East Coast, Bay of Plenty, Tauranga Harbour: Aids to Navigation |
| 93/17 | T | NZ 82 (T 82), NZ 827 (T 827), NZ 8275 (T 8275), NZ300827, NZ408275 | Kingdom of Tonga, Tongatapu, Approaches to Nuku'alofa: Aids to Navigation |
| 94/17 | T | NZ 63, NZ 632, NZ 6321, NZ300063, NZ400632, NZ506321 | East Coast, Lyttelton Harbour / Whakaraupō, Governors Bay: Light |
| 123/17 | T | NZ 56, NZ 561 | East Coast, Cape Kidnappers, Northwestwards: Outfall Pipeline Works |
| 125/17 | P | NZ 46, NZ 463, NZ 615 | North Coast, Queen Charlotte Sound / Tōtaranui: Rocks |
| 132/17 | P | NZ 532, NZ 533, NZ 5321, NZ 5324, NZ 5325, NZ 5327 | East Coast, Tamaki Strait: Rocks |
| 142/17 | T | | Maritime Safety Broadcasts - Optimum R/T Frequencies Within NAVAREA XIV |
| 150/17 | T | NZ 632, NZ 6324 | East Coast, Akaroa Harbour: Leading Lights |
| 165/17 | T | NZ 14605 (INT 605), NZ 14638 (INT 638) | Fiji, Viti Levu, Vanua Levu, Southern Lau Group & Northern Lau Group: Lights |
| 166/17 | T | NZ 7142 | West Coast, Greymouth Harbour: Depths |
| 171/17 | P | NZ 6612 | East Coast, Otago Harbour: Shoaling |

NZ 41(P)/14 SOUTH PACIFIC OCEAN – New Zealand – Chatham Islands – Depths and Rocks.

Former notice – NZ 258(P)/13 is cancelled.

1. A recent survey in the vicinity of the Chatham Islands has located numerous depths less than charted and uncharted rocks. The most significant are:

| Position | Depth | Feature |
|-----------------------------|-------|--|
| Waitangi Bay | | |
| 43° 53'.00S., 176° 58'.85W. | 9.6 | |
| 43° 52'.53S., 176° 55'.78W. | 1.3 | Underwater rock |
| 43° 53'.16S., 176° 55'.63W. | 3.0 | Underwater rock |
| 43° 50'.35S., 176° 46'.98W. | 7.9 | Underwater rock |
| 43° 48'.71S., 176° 42'.07W. | 4.7 | Uncharted Wreck |
| 43° 54'.94S., 176° 34'.04W. | 6.6 | <i>Four Fathoms</i> |
| 43° 55'.40S., 176° 32'.29W. | 2.8 | Underwater rock |
| Pitt Strait | | |
| 43° 59'.63S., 176° 22'.58W. | 12.7 | Wreck. Exclusion zone centred on position. |
| 44° 01'.31S., 176° 21'.91W. | 1.5 | Underwater rock |
| 44° 14'.31S., 176° 17'.81W. | 9.1 | |
| 44° 13'.26S., 176° 09'.78W. | 6 | |
| 44° 14'.22S., 176° 14'.23W. | 1.4 | Underwater rock |
| 44° 14'.93S., 176° 02'.31W. | 5 | |
| Kaingaroa Harbour | | |
| 43° 43'.37S., 176° 16'.78W. | 8.7 | Underwater rock <i>The Lure</i> |
| 43° 43'.92S., 176° 16'.38W. | | Rock awash |

2. Mariners are advised to exercise caution when navigating in the area.

3. Charting action will be taken in due course.

Chart affected: NZ 268

New Zealand Hydrographic Authority
NI 17/2014

NZ 155(P)/16 NEW ZEALAND – North Island – West Coast – Hokianga Harbour. Uncharted depths and rocks

1. A recent survey (November 2015) indicates numerous changes to charted features and depths in Hokianga Harbour. The most significant depths are as follows:

| Position | Depth | Feature |
|---------------------------------|-------|-------------------------------|
| (a) 35° 24'.75S., 173° 26'.19E. | 8.2 | Dangerous underwater rock |
| (b) 35° 31'.68S., 173° 21'.44E. | 4.3 | Depth |
| (c) 35° 31'.39S., 173° 23'.05E. | 5.4 | Depth |
| (d) 35° 30'.92S., 173° 22'.62E. | 8.3 | Dangerous underwater rock |
| (e) 35° 27'.71S., 173° 24'.69E. | -0.6 | Rock that covers and uncovers |
| (f) 35° 27'.09S., 173° 24'.76E. | 10.3 | Dangerous underwater rock |
| (g) 35° 26'.49S., 173° 24'.55E. | 6.0 | Dangerous underwater rock |
| (h) 35° 26'.40S., 173° 24'.55E. | 6.4 | Dangerous underwater rock |
| (i) 35° 25'.98S., 173° 24'.68E. | 14.2 | Dangerous underwater rock |
| (j) 35° 25'.53S., 173° 24'.52E. | 14.5 | Dangerous underwater rock |
| (k) 35° 23'.07S., 173° 32'.05E. | 2.4 | Depth |
| (l) 35° 22'.18S., 173° 33'.01E. | 2.2 | Dangerous underwater rock |

2. Charting action will take place in due course.

Charts affected: NZ 4212

New Zealand Hydrographic Authority
HITS 4212/44

NZ 159(T)/16 NEW ZEALAND – North Island – West Coast – Taharoa Offshore Terminal. Buoy

1. Lit yellow waverider buoy *Fl(5)Y.20s* in position 38° 12'.00S., 174° 40'.00E. has been temporarily replaced by an unlit buoy until further notice.
2. The AIS transmission to the location remains unaffected.
3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 4424, NZ404424

New Zealand Steel Ltd.
HITS 4424/9

NZ 182(P)/16 NEW ZEALAND – Chatham Islands. Area of Restricted Access

1. An Area of Restricted Access has been established around the Chatham Islands.
 - a) The area extends 3 nautical miles off all islands of the Chatham Islands and outlying dangers, from The Sisters (Rangitatahi) at 43° 33'.6S., 176° 48'.1W., to The Pyramid (Tarakoikoia) at 44° 25'.9S., 176° 14'.4W. It includes all those areas between the exclusion zones of all the islands, (Pitt Strait and the area between The Sisters (Rangitatahi) and Chatham Island). The area includes Petre Bay, and up to 3 nautical miles outside of Petre Bay, and 6 nautical miles off Hanson Bay.
 - b) The area extends 3 nautical miles around Motuhara (Bertier or the Forty Fours) 43°57'.8S., 175° 50'.4W. (about 22 nautical miles E of Cape Fournier).
2. See Annual Notice to Mariners 10 for further details.
3. Charting action will take place in due course.

Chart affected: NZ 268

Maritime New Zealand
HITS 268/170

NZ 264(T)/16 NEW ZEALAND – North Island – West Coast – Manukau Harbour Entrance. Depths

1. Former notice – NZ 190(T)/16 is cancelled.
2. All vessels should contact the Signaller at South Head. Phone (09) 235-1013, for the latest conditions.
3. Mariners should be aware that depths in the approaches to Manukau Harbour and across the bar are constantly changing.

South West Channel

- * 4. A recent survey (4 December 2016) indicates that the deepest water was found to lie within the following sectors bearing Ninepin Rock Light:
 - (a) 085° - 090.5° True. Least depth of 6.0m below CD can be expected.
5. Once over the bar mariners should alter course southwards to enter Middle Deep to avoid shoaler water on North Bank.

* *Indicates new or revised entry.*

Charts temporarily affected: NZ 4314, NZ404314

Ports of Auckland Ltd.
HITS 4314/190

NZ 267(T)/16 NEW ZEALAND – North Island – East Coast – Hawke Bay – Napier Roads. Buoy and AIS

1. A data gathering yellow wave/current buoy *Fl(5)Y.20s* is temporarily moved from 39° 27'.804S., 176° 54'.462E to 39° 28'.850S., 176° 58'.950E and is fitted with AIS identification until further notice.
2. AIS identification of “A” Buoy *Fl.G.4s* at position 39° 27'.812S., 176° 54'.529E has been temporarily removed until further notice.
3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 561, NZ 5612, NZ400561, NZ505612, NZ605612

Hawke's Bay Regional Council
HITS 5612/55

NZ 44(P)/17 NEW ZEALAND – Chatham Islands – Port Waitangi Wharf. Works

1. Mariners are advised that construction work is underway on and in the vicinity of the wharf until December 2017.
2. Mariners are advised to exercise caution when navigating in the area as uncharted structures, shoaler depths than charted and temporary lights can be expected.
3. Charting action will take place in due course.

Charts affected: NZ 268, NZ 2683, NZ 2685, NZ402683, NZ526852

Environment Canterbury & Memorial Park Alliance
HITS 2685/4

NZ 49(T)/17 NEW ZEALAND – North Island – East Coast – Tamaki Strait. Light Characteristics

1. Changes to the light characteristics of the following aids to navigation have been reported :

| <i>Position</i> | <i>Name</i> | <i>Reported Characteristics</i> |
|---------------------------------|------------------------------------|---------------------------------|
| (a) 36° 47'.57S., 175° 11'.35E. | Pakatoa Island. NW end. Wharf Head | Unlit |
| (b) 36° 47'.80S., 174° 54'.94E. | Motutapu Island | VQ(6) + LFI W 15s |
| (c) 36° 48'.53S., 174° 57'.66E. | E Cardinal | Q(3)W 5s |
| (d) 36° 48'.56S., 174° 58'.14E. | West cardinal buoy | Q(9) 15s |
| (e) 36° 49'.30S., 174° 57'.40E. | Special purpose buoy | Unlit |
| (f) 36° 51'.70S., 175° 08'.30E. | Special purpose buoy | Unlit |
| (g) 36° 51'.72S., 175° 07'.39E. | Special purpose buoy | Unlit |
| (h) 36° 53'.21S., 174° 58'.76E. | No. 6 | Unlit |
| (i) 36° 53'.27S., 174° 58'.95E. | No. 7 | Q.G |
| (j) 36° 53'.26S., 174° 58'.95E. | No. 8 | Q.R |
| (k) 36° 53'.29S., 174° 59'.03E. | W Breakwater. Off head | Oc G 4s |
| (m) 36° 53'.27S., 174° 59'.05E. | E Breakwater. Off head | Oc R 4s |

2. Pine Harbour Marina entrance channel lit beacons are reported as out of sync.
3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 532, NZ 5321, NZ 5324, NZ305321, NZ305322, NZ405321, NZ405324

NZ Light List: 3845.2, 3845.25, 3850.14, 3850.15, 3850.16, 3850.17, 3850.18, 3851

IXSurvey Pty Ltd.
HITS 5324/88

NZ 74(P)/17 NEW ZEALAND – North Island – East Coast – Bay of Plenty – Tauranga Harbour. Aids to Navigation

1. Former notice – NZ 33(P)/17 is cancelled.
2. Aids to navigation have been revised in the Tauranga Harbour. The following new aids to navigation have been installed:

| | <i>Position</i> | <i>Feature</i> | <i>Name</i> | <i>Light Characteristics</i> |
|-----|-------------------------------|--------------------------|-------------|------------------------------|
| (a) | 37° 37'.468S., 176° 10'.014E. | Port Lateral Buoy | C | Q.R |
| (b) | 37° 37'.886S., 176° 09'.699E. | Starboard Lateral Buoy | D | Iso.G.2s |
| (c) | 37° 38'.068S., 176° 09'.924E. | Port Lateral Buoy | Tanea No2 | Iso.R.2s |
| (d) | 37° 38'.160S., 176° 10'.003E. | Port Lateral Buoy | Tanea No4 | Iso.R.2s |
| (e) | 37° 38'.242S., 176° 10'.366E. | Starboard Lateral Beacon | P3 | Fl.G.3s |
| (f) | 37° 38'.265S., 176° 10'.221E. | W Cardinal Beacon | P1 | VQ(9)10s |
| (g) | 37° 38'.301S., 176° 09'.817E. | Starboard Lateral Buoy | No1 | Iso.G.2s |
| (h) | 37° 38'.313S., 176° 10'.578E. | Starboard Lateral Beacon | P5 | Q.G |
| (i) | 37° 38'.362S., 176° 10'.418E. | Port Lateral Beacon | No6 | Iso.R.2s |
| (j) | 37° 38'.398S., 176° 09'.991E. | N Cardinal Buoy | No3 | VQ |
| (k) | 37° 38'.434S., 176° 10'.675E. | S Cardinal Beacon | P7 | Q(6)+LFl.15s |
| (l) | 37° 38'.505S., 176° 10'.320E. | Starboard Lateral Buoy | No5 | Iso.G.2s |
| (m) | 37° 38'.568S., 176° 10'.490E. | Starboard Lateral Beacon | No7 | Iso.G.2s |
| (n) | 37° 38'.571S., 176° 09'.514E. | Starboard Lateral Buoy | WC3 | Q.G |
| (o) | 37° 38'.682S., 176° 09'.689E. | Port Lateral Buoy | WC2 | Q.R |
| (p) | 37° 38'.672S., 176° 10'.624E. | Starboard Lateral Beacon | No9 | Q(2)G.2s |
| (q) | 37° 38'.785S., 176° 10'.702E. | Starboard Lateral Beacon | No11 | Iso.G.2s |
| (r) | 37° 38'.912S., 176° 10'.746E. | Starboard Lateral Beacon | No13 | Iso.G.2s |
| (s) | 37° 39'.037S., 176° 10'.738E. | Starboard Lateral Beacon | No15 | Iso.G.2s |
| (t) | 37° 39'.307S., 176° 10'.598E. | Starboard Lateral Beacon | No17 | Iso.G.2s |
| (u) | 37° 39'.754S., 176° 10'.839E. | Port Lateral Beacon | No8 | Iso.R.2s |
| (v) | 37° 39'.961S., 176° 10'.589E. | Special Beacon | Town Reach | Fl.Y.5s |
| (w) | 37° 40'.125S., 176° 10'.603E. | Port Lateral Beacon | No10 | Q.R |
| (x) | 37° 40'.260S., 176° 10'.536E. | Port Lateral Beacon | No12 | Q.R |

3. The following aids to navigation have been removed:

| | <i>Position</i> | <i>Feature</i> | <i>Name</i> | <i>Light Characteristics</i> |
|-----|-------------------------------|--------------------------|-----------------|------------------------------|
| (a) | 37° 37'.490S., 176° 09'.988E. | Port Lateral Buoy | C | Q.R |
| (b) | 37° 38'.067S., 176° 09'.921E. | Port Lateral Buoy | Tanea No2 | Q.R |
| (c) | 37° 38'.159S., 176° 10'.000E. | Port Lateral Buoy | No4 | Iso.R.2s |
| (d) | 37° 38'.242S., 176° 10'.367E. | Starboard Lateral Beacon | No3 | Fl.G.3s |
| (e) | 37° 38'.266S., 176° 10'.191E. | W Cardinal Beacon | No1 | VQ(9)10s |
| (f) | 37° 38'.300S., 176° 09'.818E. | Starboard Lateral Buoy | No1 W | Q.G |
| (g) | 37° 38'.312S., 176° 10'.579E. | Starboard Lateral Beacon | No5 | Q.G |
| (h) | 37° 38'.338S., 176° 10'.352E. | Port Lateral Beacon | C2 | Q.R |
| (i) | 37° 38'.376S., 176° 10'.014E. | N Cardinal Buoy | Banks | Q |
| (j) | 37° 38'.407S., 176° 10'.519E. | Port Lateral Beacon | C4 | Q.R |
| (k) | 37° 38'.434S., 176° 10'.676E. | S Cardinal Beacon | No7 | Q(6)+LFl.15s |
| (l) | 37° 38'.451S., 176° 10'.324E. | Starboard Lateral Buoy | C1 | Q.G |
| (m) | 37° 38'.552S., 176° 10'.527E. | Starboard Lateral Beacon | C3 | Q.G |
| (n) | 37° 38'.615S., 176° 09'.544E. | Starboard Lateral Buoy | WC3 | Q.G |
| (o) | 37° 38'.630S., 176° 09'.812E. | Port Lateral Buoy | No2W | Q.R |
| (p) | 37° 38'.684S., 176° 10'.674E. | Starboard Lateral Beacon | C5 | Fl.G.3s |
| (q) | 37° 38'.810S., 176° 10'.739E. | Starboard Lateral Beacon | No11 | Q.G |
| (r) | 37° 38'.944S., 176° 10'.759E. | Lateral Beacon | No13 | Q(3)G.7.5s |
| (s) | 37° 39'.070S., 176° 10'.744E. | Starboard Lateral Beacon | No15 | Q.G |
| (t) | 37° 39'.243S., 176° 10'.669E. | Starboard Lateral Beacon | No17 | Q.G |
| (u) | 37° 39'.303S., 176° 10'.527E. | Starboard Lateral Beacon | Otumoetai 1 | Q.G |
| (v) | 37° 39'.405S., 176° 10'.580E. | Lateral Beacon | No19 The Leaner | Q(2+1)G.6s5M |
| (w) | 37° 39'.754S., 176° 10'.840E. | Lateral Beacon | No6 | Q(2)R.3s |
| (x) | 37° 39'.961S., 176° 10'.594E. | Starboard Lateral Beacon | No21 | Q.G |
| (y) | 37° 40'.122S., 176° 10'.602E. | Port Lateral Beacon | No8 | Q.R |
| (z) | 37° 40'.251S., 176° 10'.538E. | Port Lateral Beacon | No10 | Q.R |

(continued)

**NZ 74(P)/17 NEW ZEALAND – North Island – East Coast – Bay of Plenty – Tauranga Harbour. Aids to Navigation
(continued)**

4. Mariners are advised to exercise caution when navigating in the area.
5. Charting action will take place in due course.

*** Chart affected: NZ 5412**

* *Indicates new or revised entry.*

NZ Light List: 3900.4, 3902, 3902.4, 3903, 3904.32, 3904.34, 3904.36, 3904.38, 3904.7, 3904.8, 3905, 3905.2, 3905.3, 3906, 3908.1, 3908.4, 3913, 3913.5, 3920.

Bay of Plenty Regional Council
HITS 5412/382/2

**NZ 93(T)/17 SOUTH PACIFIC OCEAN – Kingdom of Tonga – Tongatapu – Approaches to Nuku'alofa. Aids to
Navigation**

1. Former notice – NZ 84(T)/17 is cancelled
2. The following aid to navigation has been reported missing:

| | <i>Position</i> | <i>Description</i> | <i>Characteristics</i> |
|-----|-----------------------------|--------------------|------------------------|
| (a) | 21° 01'.39S., 175° 11'.62W. | Beacon | Fl.G.6s |

- * 3. The light from the Hakau Mama'o beacon in position 21° 00'.04S., 175° 12'.48W. is reported as a pale green colour.
4. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 82 (T 82), NZ 827 (T 827), NZ 8275 (T 8275), NZ300827, NZ408275

BA Light List (Volume K): 4646, 4646.65

MV Queen Victoria
Ministry of Infrastructure Tonga
HITS 8275/85

**NZ 94(T)/17 NEW ZEALAND – South Island – East Coast – Lyttelton Harbour / Whakaraupō – Governors Bay.
Light**

1. The Governors Bay directional light in position 43° 37'.33S., 172° 38'.88E is temporarily operating on a reduced range.
2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 63, NZ 632, NZ 6321, NZ300063, NZ400632, NZ506321

NZ Light List: 4289

Lyttelton Port of Christchurch Ltd.
HITS 6321/157

NZ 123(T)/17 NEW ZEALAND – North Island – East Coast – Cape Kidnappers – Northwestwards. Outfall Pipeline Works.

1. Former Notice – NZ 77(T)/17 is cancelled.
2. Mariners are advised that pipeline operations are taking place in the areas bounded by the positions below until August 2017:

Hastings Outfall Pipeline
(Diving and towing operations)

- (a) 39° 34'.06S., 176° 56'.06E.
- (b) 39° 33'.85S., 176° 58'.59E.
- (c) 39° 34'.67S., 176° 59'.12E.
- (d) 39° 35'.60S., 176° 56'.62E.

Awatoto Outfall Pipeline

(Diving operations only)

- (a) 39° 31'.56S., 176° 55'.16E.
- (b) 39° 31'.36S., 176° 57'.42E.
- (c) 39° 33'.34S., 176° 57'.75E.
- (d) 39° 33'.55S., 176° 55'.54E.

3. Mariners are requested to keep 2 NM clear of these areas.

Charts temporarily affected: NZ 56, NZ 561

New Zealand Diving and Salvage Ltd.
HITS 56/50/2

NZ 125(P)/17 NEW ZEALAND – South Island – North Coast – Queen Charlotte Sound / Tōtaranui. Rocks

1. A recent survey in Queen Charlotte Sound / Tōtaranui indicates changes to charted features and depths. The most significant changes are as follows:

| <i>Position</i> | <i>Depth</i> | <i>Feature</i> |
|---------------------------------|--------------|-----------------|
| (a) 41° 04'.58S., 174° 16'.84E. | 1.6 | Underwater Rock |
| (b) 41° 04'.82S., 174° 16'.85E. | 3.2 | Underwater Rock |

2. Charting action will take place in due course.

Charts affected: NZ 46, NZ 463, NZ 615

NIWA
HITS 615/70

NZ 132(P)/17 NEW ZEALAND – North Island – East Coast – Tamaki Strait. Rocks

1. A recent survey (2016/2017) in the vicinity of Waiheke Island indicates numerous changes to charted features and depths. The most significant changes are as follows:

| <i>Position</i> | <i>Depth</i> | <i>Feature</i> |
|---------------------------------|--------------|----------------|
| (a) 36° 43'.55S., 174° 57'.17E. | -1.3 | Drying Rock |
| (b) 36° 47'.21S., 175° 09'.45E. | -0.3 | Drying Rock |
| (c) 36° 48'.46S., 175° 02'.61E. | -0.9 | Drying Rock |

2. Charting action will take place in due course.

Charts affected: NZ 532, NZ 533, NZ 5321, NZ 5324, NZ 5325, NZ 5327

New Zealand Hydrographic Authority
HITS 5324/93

NZ 142(T)/17 SOUTH PACIFIC OCEAN. Maritime Safety Broadcasts - Optimum R/T Frequencies Within NAVAREA XIV

1. The accompanying diagrams show the optimum R/T calling and working frequency bands and times for navigational warnings broadcast within 1000 nautical miles of Taupo Maritime Radio (ZLM) (38° 50'S., 176° 00'E. approx.) for the period August to October 2017.

Australian Government BoM Space Weather Services
HITS -/45

NZ 150(T)/17 NEW ZEALAND – South Island – East Coast – Akaroa Harbour. Leading Lights

1. Akaroa Harbour Leading Lights in positions 43° 49'.11S., 172° 54'.21E. (K4315) and 43° 48'.41S., 172° 53'.66E. (K4315.1) are reported unreliable.
2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 632, NZ 6324

NZ Light List: 4315, 4315.1

Environment Canterbury
HITS 6324/44

NZ 165(T)/17 SOUTH PACIFIC OCEAN – Fiji – Viti Levu, Vanua Levu, Southern Lau Group & Northern Lau Group. Lights

1. Former notice – NZ 113(T)/17 is cancelled.
- * 2. The following lights are reported as unlit:
 - (a) 18° 30'.9S., 177° 58'.8E. Beqa South West Reef
 - (b) 17° 27'.0S., 178° 57'.7E. Makogai Island
 - (c) 19° 00'.0S., 179° 52'.0W. Totoya Island. South West Point
 - (d) 19° 50'.0S., 178° 13'.2W. Vatoa Island
3. Mariners are advised to exercise caution when navigating in the area.

* *Indicates new or revised entry.*

Charts temporarily affected: NZ 14605 (INT 605), NZ 14638 (INT 638)

BA Light List (Volume K): 4695, 4733.4, 4758, 4759

Maritime Safety Authority of Fiji
HITS 14638/308

NZ 166(T)/17 NEW ZEALAND – South Island – West Coast – Greymouth Harbour. Depths

1. Former notice – NZ 131(T)/17 is cancelled.
- * 2. A recent survey (25 August 2017) indicates the following least depths below CD on the bar at the Grey River/Māwheranui entrance:

| | | | |
|-----|-------------------------------|------------|------|
| (a) | 42° 26'.306S., 171° 11'.367E. | North Lead | 4.1m |
| (b) | 42° 26'.327S., 171° 11'.371E. | Main Lead | 3.5m |
| (c) | 42° 26'.294S., 171° 11'.282E. | South Lead | 3.9m |

3. Mariners should be aware that depths in Greymouth Harbour entrance are constantly changing and should contact the Harbourmaster for the latest conditions on (027) 435 3424 or (03) 768 5666 or Greymouth Harbour Radio Ch14.

* *Indicates new or revised entry.*

Chart temporarily affected: NZ 7142

Port of Greymouth
HITS 7142/72

NZ 171(P)/17 NEW ZEALAND – South Island – East Coast – Otago Harbour – Dunedin Wharves and Goat Island/Rakiriri Southwestwards. Shoaling

3. A survey indicates that depths significantly shoaler than charted can be expected in Dunedin Wharves extending eastwards from Cross Wharf and Victoria Wharf to Beacon No. 72.
4. Depths significantly less than charted can be expected extending southwestwards from Goat Island/Rakiriri to Beacon No.3 in vicinity of 45° 49'.65S, 170° 37'.33E.
5. Mariners are advised to exercise caution when navigating in these areas.
6. Charting action will take place in due course.

Chart affected: NZ 6612

New Zealand Hydrographic Authority
HITS 6612/259