

NEW ZEALAND TEMPORARY AND PRELIMINARY NOTICES IN FORCE

(NZ NTM Edition No. 6 dated 20 March 2020)

NZ Notice	T/P	Charts Affected	Locality and Subject
55/19	P	NZ 845	South Pacific Ocean, Niue - Alofi Anchorage: Yacht Moorings
66/19	T	NZ 5322, NZ 5323	North Island - East Coast, Auckland Harbour - Queens Wharf and westwards to Westhaven Boat Harbour: Construction Works, Dredging and Marina Operations
84/19	T	NZ 61, NZ 614, NZ 6142	South Island - North Coast, Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua: Spat Catching Areas
88/19	T	NZ 5315, NZ 5316, NZ 5318	North Island - East Coast, Coromandel Peninsula - Mercury Bay: Scientific Instruments
21/20	T	NZ 7142	South Island - West Coast, Greymouth Harbour: Depths
22/20	T	NZ 43	North Island - West Coast, North Taranaki Bight: Obstructions
33/20	T	NZ 865, NZ 8655	South Pacific Ocean, Samoa - Apia Harbour: Samoa Entry Restrictions

An asterisk * in a temporary or preliminary notice indicates a new or revised entry.

NZ 55(P)/19 SOUTH PACIFIC OCEAN - Niue - Alofi Anchorage. Yacht Moorings

1. Seasonal yacht moorings have been established north and south of the wharf, bounded by the following co-ordinates:

North of wharf

- a. 19° 03'.09S., 169° 55'.33W.
- b. 19° 02'.97S., 169° 55'.27W.
- c. 19° 02'.99S., 169° 55'.23W.
- d. 19° 03'.11S., 169° 55'.29W.

South of wharf

- e. 19° 03'.32S., 169° 55'.59W.
- f. 19° 03'.13S., 169° 55'.43W.
- g. 19° 03'.18S., 169° 55'.33W.
- h. 19° 03'.32S., 169° 55'.44W.

2. Charting action will take place in due course.
3. Mariners are advised to exercise caution when navigating in the area.

Chart affected: NZ 845

Department of Transport, Niue
HITS 845/22

NZ 66(T)/19 NEW ZEALAND - North Island - East Coast - Auckland Harbour - Queens Wharf and westwards to Westhaven Boat Harbour. Construction Works, Dredging and Marina Operations

1. Former notice - NZ 56(T)/19 and NZ 59(T)/19 are cancelled.
2. Until further notice, construction works on the western edge of Queens Wharf and the Auckland Downtown Ferry Basin are underway. Lit buoys (*Fl. Y.5s*) on the western side of Queens Wharf are marking the construction area.
3. Until further notice, extensive construction works are underway in the inner and outer Viaduct Harbour area spanning westwards to the eastern extent of Westhaven Boat Harbour. The project has a 24 hour contact number - 0800 WYNYARD or contact project Stakeholder Advisor - 021896322.
4. Mariners must contact Viaduct Control (VHF Channel 73) if access is required to get to/from the Inner Viaduct Harbour.
5. Mariners should consult Auckland Transport Local Notices to Mariners for the latest information.
6. Mariners are advised to exercise caution when navigating in the area and to remain clear of all dredging and construction operations.

Charts temporarily affected: NZ 5322, NZ 5323

Auckland Transport and Wynyard Edge Alliance
HITS 5322/639

NZ 84(T)/19 NEW ZEALAND - South Island - North Coast - Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua. Spat Catching Areas

1. Seasonal spat catching areas will be established in Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua from November 2019 to May 2020. The perimeter corners are identified by cardinal marks at the following positions:

Tasman Bay / Te Tai-o-Aorere

- a. 41° 03'.32S., 173° 07'.21E.
- b. 41° 04'.55S., 173° 08'.23E.
- c. 41° 05'.60S., 173° 05'.91E.
- d. 41° 04'.38S., 173° 04'.89E.
- e. 41° 07'.99S., 173° 10'.11E.
- f. 41° 08'.41S., 173° 10'.16E.
- g. 41° 08'.18S., 173° 10'.41E.
- h. 41° 08'.22S., 173° 09'.86E.

Golden Bay / Mohua

- i. 40° 45'.09S., 172° 50'.84E.
- j. 40° 46'.02S., 172° 52'.88E.
- k. 40° 47'.62S., 172° 51'.33E.
- l. 40° 46'.66S., 172° 49'.33E.
- m. 40° 42'.28S., 172° 45'.97E.
- n. 40° 42'.39S., 172° 46'.54E.
- o. 40° 43'.46S., 172° 46'.76E.
- p. 40° 43'.35S., 172° 46'.19E.

2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 61, NZ 614, NZ 6142

Tasman Bay Ring Road Spat Catching Ltd., Golden Bay Ring Road Spat Catching Ltd.
HITS 6142/251

NZ 88(T)/19 NEW ZEALAND - North Island - East Coast - Coromandel Peninsula - Mercury Bay. Scientific Instruments

1. Scientific instruments marked by lit buoys (*Fl. Y.5s*) have been deployed in the following locations until further notice:
 - a. 36°46'.85S., 175°49'.64E.
 - b. 36°48'.98S., 175°43'.66E.

2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 5315, NZ 5316, NZ 5318

Haskoning Australia
HITS 5315/11

NZ 21(T)/20 NEW ZEALAND - South Island - West Coast - Greymouth Harbour. Depths

1. Former notice - NZ 71(T)/19 is cancelled.
2. A recent survey (13 December 2019) indicates the following least depths below CD on the bar at the Grey River/Māwheranui entrance:

<i>Position</i>	<i>Lead</i>	<i>Depth</i>
42° 26'.313S., 171° 11'.378E.	North Lead	4.6m
42° 26'.220S., 171° 11'.187E.	Main Lead	4.8m
42° 26'.248S., 171° 11'.201E.	South Lead	5.0m

3. Mariners should be aware that depths in Greymouth Harbour entrance are constantly changing and should contact the Port of Greymouth for the latest conditions on (03) 768 5666 or Greymouth Harbour Radio Ch14.

Chart temporarily affected: NZ 7142

Port of Greymouth
HITS 7142/88

NZ 22(T)/20 NEW ZEALAND - North Island - West Coast - North Taranaki Bight. Obstructions

1. Temporary, unmarked seabed ground tackle installations have been deployed the following locations until further notice:
 - a. 39° 09'.33S., 173° 08'.92E.
 - b. 39° 09'.42S., 173° 09'.19E.
 - c. 39° 09'.79S., 173° 07'.80E.
 - d. 39° 09'.93S., 173° 09'.57E.
 - e. 39° 10'.03S., 173° 07'.77E.
 - f. 39° 10'.16S., 173° 09'.54E.
 - g. 39° 10'.58S., 173° 08'.18E.
 - h. 39° 10'.68S., 173° 08'.47E.
2. Mariners, especially those involved in trawling activities, are advised to keep clear, and to exercise caution when navigating in the area.

Chart temporarily affected: NZ 43

OMV New Zealand Ltd.
HITS 43/71

NZ 33(T)/20 SOUTH PACIFIC OCEAN - Samoa - Apia Harbour. Samoa Entry Restrictions

1. Until further notice, all mariners entering Samoa are required to proceed to a temporary quarantine area at the Apia Harbour Pilot Boarding Point in position 13°47'.965S., 171°45'.517W.
2. All sea port entries will be screened at the quarantine area before the vessel docks at the wharf.
3. Further restriction details can be found at <http://www.samoagovt.ws/2020/03/health-travel-advisory-novel-coronavirus-covid-2019-effective-immediately-5/>.
4. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 865, NZ 8655

Government of Samoa
HITS 8655/47