

NEW ZEALAND TEMPORARY AND PRELIMINARY NOTICES IN FORCE

(NZ NTM Edition No. 6 dated 23 March 2018)

NZ Notice	T/P	Charts Affected	Locality and Subject
		NZ Chart, ENC Cell	
41/14	P	NZ 268	Chatham Islands: Depths and Rocks
182/16	P	NZ 268	Chatham Islands: Area of Restricted Access
267/16	T	NZ 561, NZ 5612, NZ400561, NZ505612, NZ605612	East Coast, Hawke Bay, Napier Roads: Buoy and AIS
49/17	T	NZ 532, NZ 5321, NZ 5324, NZ305321, NZ305322, NZ405321, NZ405324	East Coast, Tamaki Strait: Light Characteristics
93/17	T	NZ 82 (T 82), NZ 827 (T 827), NZ 8275 (T 8275), NZ300827, NZ408275	Kingdom of Tonga, Tongatapu, Approaches to Nuku'alofa: Aids to Navigation
132/17	P	NZ 532, NZ 533, NZ 5321, NZ 5324, NZ 5325, NZ 5327	East Coast, Tamaki Strait: Rocks
171/17	P	NZ 6612	East Coast, Otago Harbour: Shoaling
177/17	T	NZ 6422	East Coast, Approaches to Timaru: Lit Buoy
182/17	T	NZ 6321	East Coast, Lyttelton Harbour/Whakaraupō, Port of Lyttelton: Marina Construction Activity
186/17	T	NZ 56, NZ 561, NZ 5612	East Coast, Hawke Bay, Whirinaki: Pan Pac Outfall Pipeline Reserved Area
188/17	T	NZ 61, NZ 614, NZ 6142	North Coast, Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua: Spat Catching Areas
197/17	P	NZ 6612	East Coast, Otago Harbour, Port Chalmers: Wharf Works
200/17	T	NZ 23 (INT 640), NZ 26, NZ 55, NZ 56, NZ 14600 (INT 600)	East Coast, Poverty Bay to Mahia Peninsula, Eastwards: Scientific Instruments
203/17	P	NZ 268, NZ 2683, NZ 2685	Chatham Islands, Port Waitangi Wharf: Works
27/18	T	NZ 5412	East Coast, Tauranga, Town Reach: Obstruction
35/18	T		Maritime Safety Broadcasts - Optimum R/T Frequencies Within NAVAREA XIV
38/18	T	NZ 7142	West Coast, Greymouth Harbour: Depths
44/18	T	NZ 14605 (INT 605), NZ 14638 (INT 638)	Fiji, Viti Levu, Vanua Levu, Southern Lau Group & Northern Lau Group: Lights
47/18	T	NZ 82 (T 82), NZ 822 (T 822), NZ 827 (T 827), NZ 8215 (T 8215), NZ 8225 (T 8225), NZ 8235 (T 8235), NZ 8238 (T 8238), NZ 8247 (T 8247), NZ 8248 (T 8248), NZ 8259 (T 8259), NZ 8266 (T 8266), NZ 8275 (T 8275), NZ 8277 (T 8277), NZ 14631 (INT 631), NZ 14638 (INT 638)	Kingdom of Tonga: Aids to Navigation
53/18	T	NZ 43, NZ 443	West Coast, Taranaki: Scientific Instrument
54/18	T	NZ 14638 (INT 638)	Fiji, Viti Levu, Suva Harbour: Lights
60/18	T	NZ 5321	East Coast, Hauraki Gulf, Karepiro Bay: Scientific Instruments

NZ 41(P)/14 SOUTH PACIFIC OCEAN – New Zealand – Chatham Islands – Depths and Rocks.

Former notice – NZ 258(P)/13 is cancelled.

1. A recent survey in the vicinity of the Chatham Islands has located numerous depths less than charted and uncharted rocks. The most significant are:

Position	Depth	Feature
Waitangi Bay		
43° 53'.00S., 176° 58'.85W.	9.6	
43° 52'.53S., 176° 55'.78W.	1.3	Underwater rock
43° 53'.16S., 176° 55'.63W.	3.0	Underwater rock
43° 50'.35S., 176° 46'.98W.	7.9	Underwater rock
43° 48'.71S., 176° 42'.07W.	4.7	Uncharted Wreck
43° 54'.94S., 176° 34'.04W.	6.6	<i>Four Fathoms</i>
43° 55'.40S., 176° 32'.29W.	2.8	Underwater rock
Pitt Strait		
43° 59'.63S., 176° 22'.58W.	12.7	Wreck. Exclusion zone centred on position.
44° 01'.31S., 176° 21'.91W.	1.5	Underwater rock
44° 14'.31S., 176° 17'.81W.	9.1	
44° 13'.26S., 176° 09'.78W.	6	
44° 14'.22S., 176° 14'.23W.	1.4	Underwater rock
44° 14'.93S., 176° 02'.31W.	5	
Kaingaroa Harbour		
43° 43'.37S., 176° 16'.78W.	8.7	Underwater rock <i>The Lure</i>
43° 43'.92S., 176° 16'.38W.		Rock awash

2. Mariners are advised to exercise caution when navigating in the area.

3. Charting action will be taken in due course.

Chart affected: NZ 268

New Zealand Hydrographic Authority
NI 17/2014

NZ 182(P)/16 NEW ZEALAND – Chatham Islands. Area of Restricted Access

1. An Area of Restricted Access has been established around the Chatham Islands.

- a) The area extends 3 nautical miles off all islands of the Chatham Islands and outlying dangers, from The Sisters (Rangitahi) at 43° 33'.6S., 176° 48'.1W., to The Pyramid (Tarakoikoia) at 44° 25'.9S., 176° 14'.4W. It includes all those areas between the exclusion zones of all the islands, (Pitt Strait and the area between The Sisters (Rangitahi) and Chatham Island). The area includes Petre Bay, and up to 3 nautical miles outside of Petre Bay, and 6 nautical miles off Hanson Bay.
- b) The area extends 3 nautical miles around Motuhara (Bertier or the Forty Fours) 43°57'.8S., 175° 50'.4W. (about 22 nautical miles E of Cape Fournier).

2. See Annual Notice to Mariners 10 for further details.

3. Charting action will take place in due course.

Chart affected: NZ 268

Maritime New Zealand
HITS 268/170

NZ 267(T)/16 NEW ZEALAND – North Island – East Coast – Hawke Bay – Napier Roads. Buoy and AIS

1. A data gathering yellow wave/current buoy *FI(5)Y.20s* is temporarily moved from 39° 27'.804S., 176° 54'.462E to 39° 28'.850S., 176° 58'.950E and is fitted with AIS identification until further notice.
2. AIS identification of "A" Buoy *FI.G.4s* at position 39° 27'.812S., 176° 54'.529E has been temporarily removed until further notice.
3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 561, NZ 5612, NZ400561, NZ505612, NZ605612

Hawke's Bay Regional Council
HITS 5612/55

NZ 49(T)/17 NEW ZEALAND – North Island – East Coast – Tamaki Strait. Light Characteristics

1. Changes to the light characteristics of the following aids to navigation have been reported :

<i>Position</i>	<i>Name</i>	<i>Reported Characteristics</i>
(a) 36° 47'.57S., 175° 11'.35E.	Pakatoa Island. NW end. Wharf Head	Unlit
(b) 36° 47'.80S., 174° 54'.94E.	Motutapu Island	VQ(6) + LFI W 15s
(c) 36° 48'.53S., 174° 57'.66E.	E Cardinal	Q(3)W 5s
(d) 36° 48'.56S., 174° 58'.14E.	West cardinal buoy	Q(9) 15s
(e) 36° 49'.30S., 174° 57'.40E.	Special purpose buoy	Unlit
(f) 36° 51'.70S., 175° 08'.30E.	Special purpose buoy	Unlit
(g) 36° 51'.72S., 175° 07'.39E.	Special purpose buoy	Unlit
(h) 36° 53'.21S., 174° 58'.76E.	No. 6	Unlit
(i) 36° 53'.27S., 174° 58'.95E.	No. 7	Q.G
(j) 36° 53'.26S., 174° 58'.95E.	No. 8	Q.R
(k) 36° 53'.29S., 174° 59'.03E.	W Breakwater. Off head	Oc G 4s
(m) 36° 53'.27S., 174° 59'.05E.	E Breakwater. Off head	Oc R 4s

2. Pine Harbour Marina entrance channel lit beacons are reported as out of sync.
3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 532, NZ 5321, NZ 5324, NZ305321, NZ305322, NZ405321, NZ405324

NZ Light List: 3845.2, 3845.25, 3850.14, 3850.15, 3850.16, 3850.17, 3850.18, 3851

IXSurvey Pty Ltd.
HITS 5324/88

NZ 93(T)/17 SOUTH PACIFIC OCEAN – Kingdom of Tonga – Tongatapu – Approaches to Nuku'alofa. Aids to Navigation

1. Former notice – NZ 84(T)/17 is cancelled
2. The following aid to navigation has been reported missing:

<i>Position</i>	<i>Description</i>	<i>Characteristics</i>
(a) 21° 01'.39S., 175° 11'.62W.	Beacon	FI.G.6s

- * 3. The light from the Hakau Mama'o beacon in position 21° 00'.04S., 175° 12'.48W. is reported as a pale green colour.
4. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 82 (T 82), NZ 827 (T 827), NZ 8275 (T 8275), NZ300827, NZ408275

BA Light List (Volume K): 4646, 4646.65

MV Queen Victoria
Ministry of Infrastructure Tonga
HITS 8275/85

NZ 132(P)/17 NEW ZEALAND – North Island – East Coast – Tamaki Strait. Rocks

1. A recent survey (2016/2017) in the vicinity of Waiheke Island indicates numerous changes to charted features and depths. The most significant changes are as follows:

<i>Position</i>	<i>Depth</i>	<i>Feature</i>
(a) 36° 43'.55S., 174° 57'.17E.	-1.3	Drying Rock
(b) 36° 47'.21S., 175° 09'.45E.	-0.3	Drying Rock
(c) 36° 48'.46S., 175° 02'.61E.	-0.9	Drying Rock

2. Charting action will take place in due course.

Charts affected: NZ 532, NZ 533, NZ 5321, NZ 5324, NZ 5325, NZ 5327

New Zealand Hydrographic Authority
HITS 5324/93

NZ 171(P)/17 NEW ZEALAND – South Island – East Coast – Otago Harbour – Dunedin Wharves and Goat Island/Rakiriri Southwestwards. Shoaling

1. A survey indicates that depths significantly shoaler than charted can be expected in Dunedin Wharves extending eastwards from Cross Wharf and Victoria Wharf to Beacon No. 72.
2. Depths significantly less than charted can be expected extending southwestwards from Goat Island/Rakiriri to Beacon No.3 in vicinity of 45° 49'.65S, 170° 37'.33E.
3. Mariners are advised to exercise caution when navigating in these areas.
4. Charting action will take place in due course.

Chart affected: NZ 6612

New Zealand Hydrographic Authority
HITS 6612/259

NZ 177(T)/17 NEW ZEALAND – South Island – East Coast – Approaches to Timaru. Lit Buoy

1. The red port Outer Channel lit buoy, *Fl(3)R. 10s* in position 44° 23'.12S., 171° 17'.36E. has been removed for maintenance until further notice.
2. Mariners are advised to exercise caution when navigating in the area.

Chart temporarily affected: NZ 6422

PrimePort Timaru
HITS 6422/96

NZ 182(T)/17 NEW ZEALAND – South Island – East Coast – Lyttelton Harbour/Whakaraupō – Port of Lyttelton. Marina Construction Activity

1. Marina construction barges and floating plant will be undertaking construction activity in the area to the west of the limit bounded by the following co-ordinates, until further notice:
 - (a) 43° 36'.242S., 172° 42'.958E. (coastline)
 - (b) 43° 36'.441S., 172° 42'.791E. (coastline)
2. Un-lit piles, moored vessels, and other obstructions maybe encountered at any time.
3. The contractor working in the area can be contacted via VHF radio channel 12 or on 021 227 2191.
4. Mariners are advised to exercise caution when navigating in the area.

Chart temporarily affected: NZ 6321

Lyttelton Port of Christchurch
HITS 6321/167

NZ 186(T)/17 NEW ZEALAND – North Island – East Coast – Hawke Bay – Whirinaki. Pan Pac Outfall Pipeline Reserved Area

1. Former Notice – NZ 174(T)/17 is cancelled.
2. A reserved area for the exclusive use of construction traffic has been established until March 2018, bounded by the following co-ordinates:
 - (a) 39° 22'.31S., 176° 53'.95E.
 - (b) 39° 22'.90S., 176° 55'.75E.
 - (c) 39° 23'.85S., 176° 55'.25E.
 - (d) 39° 23'.41S., 176° 53'.35E.
3. Mariners are requested to keep clear of this area and exercise caution when navigating in the vicinity.

Charts temporarily affected: NZ 56, NZ 561, NZ 5612

New Zealand Diving & Salvage Ltd. & Hawke's Bay Regional Council
HITS 5612/61

NZ 188(T)/17 NEW ZEALAND – South Island – North Coast – Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua. Spat Catching Areas

1. Seasonal spat catching areas will be established in Tasman Bay / Te Tai-o-Aorere and Golden Bay / Mohua from November 2017 to May 2018. The perimeter corners are identified by cardinal marks at the following positions:

Tasman Bay / Te Tai-o-Aorere	(a) 41° 03'.32S., 173° 07'.21E.
	(b) 41° 04'.38S., 173° 04'.89E.
	(c) 41° 04'.55S., 173° 08'.23E.
	(d) 41° 05'.60S., 173° 05'.91E.
	(e) 41° 08'.53S., 173° 10'.93E.
	(f) 41° 08'.66S., 173° 11'.15E.
	(g) 41° 08'.72S., 173° 10'.70E.
	(h) 41° 08'.85S., 173° 10'.92E.
Golden Bay / Mohua	(i) 40° 45'.09S., 172° 50'.84E.
	(j) 40° 46'.03S., 172° 52'.88E.
	(k) 40° 46'.66S., 172° 49'.33E.
	(l) 40° 47'.62S., 172° 51'.33E.
	(m) 40° 42'.52S., 172° 46'.03E.
	(n) 40° 42'.58S., 172° 46'.58E.
	(o) 40° 43'.35S., 172° 46'.19E.
	(p) 40° 43'.47S., 172° 46'.76E.

2. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 61, NZ 614, NZ 6142

Tasman Bay Ring Road Spat Catching Ltd., Golden Bay Ring Road Spat Catching Ltd., Challenger Scallop Enhancement Co. Ltd. & Golden Bay Mussels Ltd.
HITS 6144/53

NZ 197(P)/17 NEW ZEALAND – South Island – East Coast – Otago Harbour – Port Chalmers. Wharf Works

1. Mariners are advised that construction work is underway in the vicinity of the Multi Purpose Wharf until December 2018.
2. Mariners are advised to keep well clear of the area and to contact Harbour Control on VHF channel 14 for updates on water craft activity at the construction site.
3. The fixed green (neon) light at the north east corner of the existing wharf (45° 48'.58S., 170° 37'.67E.) has been temporarily removed.
4. Charting action will take place in due course.

Charts affected: NZ 6612

NZ Light List: 4369.86

New Zealand Hydrographic Authority
HITS 6612/266

NZ 200(T)/17 NEW ZEALAND – North Island – East Coast – Poverty Bay to Mahia Peninsula, Eastwards. Scientific Instruments

- * 1. Former notice – NZ 193(T)/17 is cancelled.
2. Scientific instruments have been deployed on the seafloor at the following co-ordinates, until October 2018:

- (a) 38° 42'.44S., 178° 39'.68E.
- (b) 38° 42'.65S., 178° 39'.68E.
- (c) 38° 43'.51S., 178° 53'.66E.
- (d) 38° 51'.01S., 178° 52'.34E.
- (e) 38° 53'.59S., 178° 45'.29E.
- (f) 38° 54'.70S., 178° 59'.09E.
- (g) 39° 13'.96S., 178° 26'.04E.
- (h) 39° 16'.53S., 178° 43'.97E.
- (i) 39° 17'.82S., 178° 39'.19E.
- (j) 39° 18'.75S., 178° 32'.35E.

Mariners engaged in seabed trawling activities are requested to remain 2.5NM clear at all times.

- * 3. Scientific instruments will be deployed on the seafloor in an area bounded by the following co-ordinates, from 16 December 2017 to 30 April 2018:

- (a) 38° 37'.11S., 178° 30'.90E.
- (b) 38° 53'.73S., 179° 06'.54E.
- (c) 39° 00'.22S., 179° 01'.56E.
- (d) 38° 43'.60S., 178° 25'.86E.

Mariners engaged in seabed trawling activities are requested to remain clear at all times.

Charts temporarily affected: NZ 23 (INT 640), NZ 26, NZ 55, NZ 56, NZ 14600 (INT 600)

- * *Indicates new or revised entry.*

GNS Science
HITS 55/127/3

NZ 203(P)/17 NEW ZEALAND – Chatham Islands – Port Waitangi Wharf. Works

1. Former notice – NZ 44(P)/17 is cancelled.
2. Mariners are advised that construction work is underway on and in the vicinity of the wharf until March 2018.
3. Mariners are advised to exercise caution when navigating in the area as uncharted structures, shoaler depths than charted and temporary lights can be expected.
4. Charting action will take place in due course.

Charts affected: NZ 268, NZ 2683, NZ 2685

Environment Canterbury & Memorial Park Alliance
HITS 2683/1

NZ 27(T)/18 NEW ZEALAND – North Island – East Coast – Tauranga – Town Reach. Obstruction

1. A temporary inflatable waterpark has been established in the vicinity of 37° 41'.00S., 176° 10'.27E. until further notice.
2. The seaward perimeter corners are identified by QY lights.
3. Mariners are advised to exercise caution when navigating in the area.

Chart temporarily affected: NZ 5412

Bay of Plenty Regional Council Toi Moana
HITS 5412/391

NZ 35(T)/18 SOUTH PACIFIC OCEAN. Maritime Safety Broadcasts - Optimum R/T Frequencies Within NAVAREA XIV

1. Former notice - 189(T)/17 is cancelled.
2. The accompanying diagrams show the optimum R/T calling and working frequency bands and times for navigational warnings broadcast within 1000 nautical miles of Taupo Maritime Radio (ZLM) (38° 50'S., 176° 00'E. approx.) for the period February to April 2018.

Australian Government BoM Space Weather Services
HITS -/56

NZ 38(T)/18 NEW ZEALAND – South Island – West Coast – Greymouth Harbour. Depths

1. Former notice – NZ 204(T)/17 is cancelled.
- * 2. A recent survey (22 January 2018) indicates the following least depths below CD on the bar at the Grey River/Māwheranui entrance:

(a)	42° 26'.319S., 171° 11'.390E.	North Lead	3.8m
(b)	42° 26'.307S., 171° 11'.336E.	Main Lead	4.1m
(c)	42° 26'.326S., 171° 11'.340E.	South Lead	3.9m

3. Mariners should be aware that depths in Greymouth Harbour entrance are constantly changing and should contact the Harbourmaster for the latest conditions on (027) 435 3424 or (03) 768 5666 or Greymouth Harbour Radio Ch14.

* *Indicates new or revised entry.*

Chart temporarily affected: NZ 7142

Port of Greymouth
HITS 7142/75

NZ 44(T)/18 SOUTH PACIFIC OCEAN – Fiji – Viti Levu, Vanua Levu, Southern Lau Group & Northern Lau Group. Lights

1. Former notice – NZ 165(T)/17 is cancelled.
- * 2. The following lights are reported as unlit:

- (a) 18° 30'.9S., 177° 58'.8E. Beqa South West Reef
- (b) 17° 27'.0S., 178° 57'.7E. Makogai Island
- (c) 19° 00'.0S., 179° 52'.0W. Totoya Island. South West Point
- (d) 19° 50'.0S., 178° 13'.2W. Vatoa Island
- (e) 16° 44'.3S., 179° 06'.4W. Welagilala Island

3. Mariners are advised to exercise caution when navigating in the area.

* *Indicates new or revised entry.*

Charts temporarily affected: NZ 14605 (INT 605), NZ 14638 (INT 638)

BA Light List (Volume K): 4695, 4733.4, 4752, 4758, 4759

Maritime Safety Authority of Fiji
HITS 14638/316

NZ 47(T)/18 SOUTH PACIFIC OCEAN – Kingdom of Tonga. Aids to Navigation

1. Due to cyclone Gita aftermath, aids to navigation may be unreliable.
2. Mariners are advised to navigate with caution in coastal waters and approaches to harbours.

Charts temporarily affected: NZ 82 (T 82), NZ 822 (T 822), NZ 827 (T 827), NZ 8215 (T 8215), NZ 8225 (T 8225), NZ 8235 (T 8235), NZ 8238 (T 8238), NZ 8247 (T 8247), NZ 8248 (T 8248), NZ 8259 (T 8259), NZ 8266 (T 8266), NZ 8275 (T 8275), NZ 8277 (T 8277), NZ 14631 (INT 631), NZ 14638 (INT 638)

New Zealand Hydrographic Authority
HITS 82/1021

NZ 53(T)/18 NEW ZEALAND – North Island – West Coast – Taranaki. Scientific Instrument

1. A scientific instrument has been deployed on the seafloor at position 39° 06'.21S., 173° 35'.04E., until May 2018.
2. Mariners engaged in seabed trawling activities are requested to remain 1 NM clear at all times.

Charts temporarily affected: NZ 43, NZ 443

Shell Taranaki Limited
HITS 443/17

NZ 54(T)/18 SOUTH PACIFIC OCEAN – Fiji – Viti Levu – Suva Harbour. Lights

1. The leading lights, Ldg 2Oc.R.15M, marking the entrance to Suva Harbour in position 18° 06'.40S., 178° 24'.48E. have been reverted to, Ldg 2Oc.Bu.15M, until further notice.

Chart temporarily affected: NZ 14638 (INT 638)

BA Light List (Volume K): 4672, 4672.1

Maritime Safety Authority of Fiji
HITS 14638/317

NZ 60(T)/18 NEW ZEALAND – North Island – East Coast – Hauraki Gulf – Karepiro Bay. Scientific Instruments

1. Scientific instruments marked by lit buoys, (*Fl. Y.5s*), have been deployed in the following locations, until 15 June 2018:

Yellow can buoys:

- (a) 36° 39'.12S., 174° 45'.12E.
- (b) 36° 38'.94S., 174° 44'.58E.
- (c) 36° 39'.48S., 174° 44'.64E.

Red spherical buoys:

- (d) 36° 39'.06S., 174° 44'.40E.
- (e) 36° 39'.54S., 174° 44'.52E.

2. Mariners are advised to exercise caution when navigating in the area.

Chart temporarily affected: NZ 5321

DHI New Zealand
HITS 5321/89