

NZ 103(P)/18 SOUTH PACIFIC OCEAN – Samoa – Apia Harbour. Aids to Navigation and Port Development

1. Mariners are advised that the following lit buoys have been deployed in Apia Harbour Entrance:

Name	Colour	Light	Position
Channel Marker Buoys:			
(a) No. 1	Green	Fl.G.4s	13° 48'.910S., 171° 45'.902W.
(b) No. 2	Red	Fl.R.4s	13° 49'.104S., 171° 45'.653W.
(c) No. 3	Green	Fl.G.4s	13° 49'.368S., 171° 45'.965W.

Special Marker Buoys:			
(d) No. 1	Yellow	Fl.Y.4s	13° 49'.068S., 171° 45'.974W.
(e) No. 2	Yellow	Fl.Y.4s	13° 49'.480S., 171° 45'.764W.

2. Construction work is underway in the vicinity of the Main Wharf bounded by the following co-ordinates:

- (f) 13° 49'.576S., 171° 45'.728W.
- (g) 13° 49'.685S., 171° 45'.714W.
- (h) 13° 49'.617S., 171° 45'.685W.

3. Mariners are advised to exercise caution when navigation in the area.

4. Charting action will take place in due course

Chart affected: NZ 8655

Samoan Ministry of Works, Transport and Infrastructure
HITS 8655/45