

NZ 129(T)/18 NEW ZEALAND - North Island - East Coast – Tamaki Strait. Lights

1. The following lights are reported as unlit:

	<i>Position</i>	<i>Name</i>
a.	36° 47'.57S., 175° 11'.35E.	Pakatoa Island. NW end. Wharf Head
b.	36° 49'.30S., 174° 57'.40E.	<i>Special purpose buoy</i>
c.	36° 51'.70S., 175° 08'.30E.	<i>Special purpose buoy</i>
d.	36° 51'.72S., 175° 07'.39E.	<i>Special purpose buoy</i>

2. Lit West cardinal buoy in position 36° 48'.56S., 174° 58'.14E. has been reported with the characteristic of Q(9)15s.

3. Mariners are advised to exercise caution when navigating in the area.

Charts temporarily affected: NZ 532, NZ 533, NZ 5324, NZ 5327

NZ Light List: 3851

IXSurvey Pty Ltd.
HITS 532/465