

Record of Survey - DP 581460

Survey Number	DP 581460
Surveyor Reference	6131 - Gap Road Services Ltd - Dejoux Rd - Winton
Surveyor	Merryn Kay Maguire
Survey Firm	Bonisch Consultants Ltd
Surveyor Declaration	I Merryn Kay Maguire, being a licensed cadastral surveyor, certify that-- (a) this dataset provided by me and its related survey are accurate, correct and in accordance with the Cadastral Survey Act 2002 and Cadastral Survey Rules 2021; and (b) the survey was undertaken by me or under my personal direction. Declared on 01 Dec 2022 09:50 AM

Survey Details

Dataset Description	Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.		
Purpose	LT Subdivision		
Status	Deposited	Type	Survey
Land District	Southland	Survey Class	Class A
Meridional Circuit	Bluff 2000	Vertical Datum	None

Survey Dates

Surveyed Date	22/08/2022	Certified Date	01/12/2022
Submitted Date	01/12/2022 09:50:23	Survey Approval Date	13/12/2022
Deposit Date	01/12/2022		

Referenced Surveys

Survey Number	Land District	Bearing Correction
DP 80	Southland	
SO 11260	Southland	0°00'00"
DP 322521	Southland	0°00'00"
DP 335821	Southland	0°00'00"
DP 500853	Southland	0°00'00"
DP 502767	Southland	0°00'00"

Territorial Authorities

Southland District

Comprised In

RT 753792

Created Parcels

Parcels	Parcel Intent	Area	RT Reference
Lot 1 Deposited Plan 581460	Fee Simple Title	0.0675 Ha	1084431
Lot 2 Deposited Plan 581460	Fee Simple Title	0.0687 Ha	1084432
Lot 3 Deposited Plan 581460	Fee Simple Title	0.0855 Ha	1084433
Lot 4 Deposited Plan 581460	Fee Simple Title	0.0897 Ha	1084434
Lot 5 Deposited Plan 581460	Fee Simple Title	0.0800 Ha	1084435
Lot 6 Deposited Plan 581460	Fee Simple Title	0.0597 Ha	1084436

Record of Survey - DP 581460

Created Parcels

Parcels	Parcel Intent	Area	RT Reference
Lot 7 Deposited Plan 581460	Fee Simple Title	0.0598 Ha	1084437
Lot 8 Deposited Plan 581460	Fee Simple Title	0.0717 Ha	1084438
Lot 9 Deposited Plan 581460	Fee Simple Title	0.0718 Ha	1084439
Lot 10 Deposited Plan 581460	Fee Simple Title	1.3856 Ha	1084442
Lot 11 Deposited Plan 581460	Fee Simple Title	1.3862 Ha	1084442
Lot 12 Deposited Plan 581460	Fee Simple Title	2.0094 Ha	1084442
Lot 13 Deposited Plan 581460	Fee Simple Title	2.0232 Ha	1084442
Lot 100 Deposited Plan 581460	Fee Simple Title	0.3466 Ha	1084442
Area A Deposited Plan 581460	Easement		
Area B Deposited Plan 581460	Easement		
Area C Deposited Plan 581460	Easement		
Area D Deposited Plan 581460	Easement		
Area E Deposited Plan 581460	Easement		
Area F Deposited Plan 581460	Easement		
Area G Deposited Plan 581460	Easement		
Area H Deposited Plan 581460	Easement		
Area I Deposited Plan 581460	Easement		
Area J Deposited Plan 581460	Easement		
Total Area		7.8054 Ha	

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
SS 39 SO 11260	IT 1 DP 360565	ob0	269°49'45" M			95.59 M		
IT 1 DP 360565	IB 1 DP 500853	ob33	269°49'45" M			118.41 M		
IB 1 DP 500853	SS 40 SO 11260	ob4	269°49'45" M			25.86 M		
SS 39 SO 11260	IT III DP 11530	ob1	269°49'45" M			37.62 M		
IT III DP 11530	IT 1 DP 360565	ob119	269°49'45" M			57.97 M		
IT 1 DP 360565	IT I DP 581460	ob34	180°48'20" M			204.94 M		
IT I DP 581460	IB 1 DP 500853	ob124	330°32'45" M			234.93 M		
IT I DP 581460	IT II DP 581460	ob125	188°06'15" M			169.92 M		
IT II DP 581460	IB 1 DP 500853	ob133	346°12'00" M			383.88 M		
IB 1 DP 500853	IT VI DP 4596	ob5	181°02'30" A	DP 502767	0°00'00"	212.54 A	DP 502767	
IT VI DP 4596	IB II DP 500853	ob19	340°52'40" A	DP 500853	0°00'00"	224.68 A	DP 500853	
IB II DP 500853	SS 40 SO 11260	ob23	89°49'45" A	DP 502767	0°00'00"	51.59 A	DP 502767	
IB 1 DP 500853	PEG E DP 500853	ob6	98°10'00" A	DP 500853	0°00'00"	100.72 A	DP 500853	
IB 1 DP 500853	PEG A DP 500853	ob7	169°32'00" M			14.84 M		
IT VI DP 4596	DISK 8 DP 581460	ob20	91°54'00" A	DP 500853	0°00'00"	104.45 A	DP 500853	
IT VI DP 4596	PEG B DP 500853	ob21	102°09'00" A	DP 500853	0°00'00"	6.94 A	DP 500853	
IT VI DP 4596	POST C DP 500853	ob22	130°53'45" A	DP 500853	0°00'00"	5.71 A	DP 500853	
PEG A DP 500853	PEG 38 DP 581460	ob25	89°49'45" A	DP 502767	0°00'00"	23.04 C		Class A
PEG 38 DP 581460	UNMK 39 DP 581460	ob80	89°49'45" A	DP 502767	0°00'00"	3.00 C		Class A
UNMK 39 DP 581460	PEG 40 DP 581460	ob81	89°49'45" A	DP 502767	0°00'00"	3.00 C		Class A
PEG 40 DP 581460	PEG 11 DP 581460	ob82	89°49'45" A	DP 502767	0°00'00"	23.22 C		Class A
PEG 11 DP 581460	PEG E DP 500853	ob29	89°49'45" A	DP 502767	0°00'00"	44.74 A	DP 502767	
PEG E DP 500853	PEG B DP 502767	ob24	179°45'55" A	DP 502767	0°00'00"	59.60 A	DP 502767	Class A
PEG B DP 502767	UNMK 15 DP 581460	ob30	179°45'55" A	DP 502767	0°00'00"	6.00 C		Class A
UNMK 15 DP 581460	DISK 8 DP 581460	ob48	179°45'55" A	DP 502767	0°00'00"	136.07 C		Class A
DISK 8 DP 581460	UNMK 63 DP 581460	ob26	269°50'30" A	DP 500853	0°00'00"	89.61 C		Class A
UNMK 63 DP 581460	POST C DP 500853	ob136	269°50'30" A	DP 500853	0°00'00"	10.47 C		Class A
POST C DP 500853	PEG B DP 500853	ob28	47°21'00" A	DP 500853	0°00'00"	3.36 A	DP 500853	Class A
PEG B DP 500853	DISK 43 DP 581460	ob27	359°56'00" A	DP 500853	0°00'00"	140.78 C		Class A

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
DISK 43 DP 581460	DISK 42 DP 581460	ob86	359°56'00"	A DP 500853	0°00'00"	29.36 C		Class A
DISK 42 DP 581460	PEG A DP 500853	ob84	359°56'00"	A DP 500853	0°00'00"	29.25 C		Class A
PEG B DP 502767	PEG C DP 502767	ob31	269°04'00"	A DP 502767	0°00'00"	43.89 A	DP 502767	Class A
PEG C DP 502767	PEG 41 DP 581460	ob32	358°57'00"	A DP 502767	0°00'00"	30.84 C		Class A
PEG 41 DP 581460	PEG 11 DP 581460	ob83	358°57'00"	A DP 502767	0°00'00"	29.35 C		Class A
IB 1 DP 500853	PEG 11 DP 581460	ob8	104°43'20"	M		56.82 M		
IB 1 DP 500853	PEG C DP 502767	ob9	143°05'00"	M		93.33 M		
IT 1 DP 360565	PEG E DP 500853	ob35	231°56'00"	M		23.77 M		
IT 1 DP 360565	PEG B DP 502767	ob36	193°57'40"	M		76.52 M		
SS 11 SO 11260	SS 39 SO 11260	ob50	269°49'55"	A SO 11260	0°00'00"	367.485 A	SO 11260	
SS 39 SO 11260	IT 4 DP 322521	ob2	182°54'35"	A DP 322521	0°00'00"	224.80 A	DP 322521	
IT 4 DP 322521	SS 11 SO 11260	ob51	59°13'55"	A DP 322521	0°00'00"	440.97 A	DP 322521	
SS 39 SO 11260	IS II DP 10453	ob3	179°45'30"	A DP 500853	0°00'00"	14.60 A	DP 500853	
IS II DP 10453	DISK 19 DP 581460	ob54	269°49'45"	A DP 500853	0°00'00"	12.58 A	DP 500853	
DISK 19 DP 581460	PEG 37 DP 581460	ob55	179°45'30"	A DP 500853	0°00'00"	20.00 C		Class A
PEG 37 DP 581460	PEG 20 DP 581460	ob79	179°45'30"	A DP 500853	0°00'00"	20.00 C		Class A
PEG 20 DP 581460	PEG J DP 322521	ob57	179°48'00"	A DP 500853	0°00'00"	161.70 A	DP 500853	Class A
PEG J DP 322521	IT 4 DP 322521	ob58	177°24'00"	A DP 322521	0°00'00"	8.18 A	DP 322521	
DISK 19 DP 581460	PEG 36 DP 581460	ob56	269°49'45"	A DP 500853	0°00'00"	29.89 C		Class A
PEG 36 DP 581460	UNMK 35 DP 581460	ob78	269°49'45"	A DP 500853	0°00'00"	3.00 C		Class A
UNMK 35 DP 581460	PEG 34 DP 581460	ob77	269°49'45"	A DP 500853	0°00'00"	3.00 C		Class A
PEG 34 DP 581460	PEG 33 DP 581460	ob76	269°49'45"	A DP 500853	0°00'00"	29.89 C		Class A
PEG 33 DP 581460	PEG 32 DP 581460	ob75	269°49'45"	A DP 500853	0°00'00"	20.00 C		Class A
PEG 32 DP 581460	PEG E DP 500853	ob73	269°49'45"	A DP 500853	0°00'00"	16.00 C		Class A
IT 4 DP 322521	IT 2 DP 322521	ob52	129°20'00"	A DP 322521	0°00'00"	240.70 A	DP 322521	
IT 2 DP 322521	IT 3 DP 322521	ob60	259°56'00"	A DP 322521	0°00'00"	179.74 A	DP 322521	
IT 3 DP 322521	IT 4 DP 322521	ob61	357°08'15"	A DP 322521	0°00'00"	184.21 A	DP 322521	

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
IT 3 DP 322521	PEG H DP 322521	ob62	224°34'00"	A DP 322521	0°00'00"	12.63 A	DP 322521	
IT 4 DP 322521	PEG I DP 322521	ob53	180°00'45"	A DP 322521	0°00'00"	91.58 A	DP 322521	
PEG J DP 322521	PEG I DP 322521	ob59	179°48'00"	A DP 322521	0°00'00"	99.75 A	DP 322521	Class A
PEG I DP 322521	PEG H DP 322521	ob64	179°48'00"	A DP 322521	0°00'00"	101.40 A	DP 322521	Class A
IT 3 DP 322521	IT 2 DP 335821	ob63	253°23'45"	A DP 335821	0°00'00"	107.28 A	DP 335821	
IT 2 DP 335821	IT 3 DP 335821	ob65	269°35'05"	A DP 335821	0°00'00"	99.58 A	DP 335821	
IT 3 DP 335821	IT 4 DP 335821	ob66	153°06'05"	A DP 335821	0°00'00"	188.71 A	DP 335821	
IT 4 DP 335821	IT 1 DP 335821	ob68	31°12'20"	A DP 335821	0°00'00"	206.82 A	DP 335821	
IT 1 DP 335821	IT 3 DP 322521	ob69	23°24'00"	A DP 335821	0°00'00"	24.83 A	DP 335821	
IT 3 DP 335821	PEG 3a DP 335821	ob67	325°50'30"	A DP 335821	0°00'00"	14.19 A	DP 335821	
PEG 3a DP 335821	PEG 31 DP 581460	ob70	359°44'00"	C		10.06 A	DP 80	
PEG 31 DP 581460	POST C DP 500853	ob71	359°44'00"	C		201.19 C		Class A
PEG 31 DP 581460	UNMK 67 DP 581460	ob72	89°50'20"	A DP 335821	0°00'00"	9.78 C		Class A
UNMK 67 DP 581460	IS 44 DP 581460	ob141	89°50'20"	A DP 335821	0°00'00"	89.88 C		Class A
IS 44 DP 581460	PEG H DP 322521	ob88	89°50'20"	A DP 335821	0°00'00"	101.88 C		Class A
DISK 43 DP 581460	UNMK 60 DP 581460	ob87	89°56'00"	C		23.15 C		Class A
UNMK 60 DP 581460	PEG 45 DP 581460	ob123	89°56'00"	C		3.00 C		Class A
PEG 45 DP 581460	PEG C DP 502767	ob89	93°04'00"	C		27.19 C		Class A
PEG 45 DP 581460	DISK 46 DP 581460	ob90	359°50'00"	C		24.35 C		Class A
DISK 46 DP 581460	UNMK 39 DP 581460	ob91	359°50'00"	C		34.30 C		Class A
DISK 42 DP 581460	PEG 47 DP 581460	ob85	89°56'00"	C		23.09 C		Class A
PEG 47 DP 581460	DISK 46 DP 581460	ob93	148°54'00"	C		5.84 C		Class A
DISK 46 DP 581460	PEG 48 DP 581460	ob92	30°49'00"	C		5.83 C		Class A
PEG 48 DP 581460	PEG 41 DP 581460	ob96	89°56'00"	C		23.67 C		Class A
PEG 47 DP 581460	PEG 38 DP 581460	ob94	359°50'00"	C		29.29 C		Class A
PEG 48 DP 581460	PEG 40 DP 581460	ob97	359°50'00"	C		29.30 C		Class A

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
PEG 47 DP 581460	UNMK 60 DP 581460	ob95	179°50'00" C			29.36 C		Class A
PEG 32 DP 581460	DISK 49 DP 581460	ob74	179°45'55" C			40.00 C		Class A
DISK 49 DP 581460	UNMK 69 DP 581460	ob98	179°45'55" C			6.00 C		Class A
UNMK 69 DP 581460	DISK 50 DP 581460	ob143	179°45'55" C			155.67 C		Class A
DISK 50 DP 581460	PEG 51 DP 581460	ob100	179°45'55" C			15.00 C		Class A
PEG 51 DP 581460	PEG 52 DP 581460	ob102	269°50'00" C			16.00 C		Class A
PEG 52 DP 581460	DISK 8 DP 581460	ob103	359°45'55" C			15.00 C		Class A
PEG 52 DP 581460	IS 44 DP 581460	ob104	179°51'40" C			186.18 C		Class A
DISK 50 DP 581460	PEG J DP 322521	ob101	89°51'00" C			85.68 C		Class A
DISK 49 DP 581460	PEG 54 DP 581460	ob99	89°49'45" C			20.00 C		Class A
PEG 54 DP 581460	PEG 53 DP 581460	ob107	89°49'45" C			32.85 C		Class A
PEG 53 DP 581460	UNMK 68 DP 581460	ob105	89°49'45" C			3.00 C		Class A
UNMK 68 DP 581460	PEG 20 DP 581460	ob142	89°49'45" C			29.94 C		Class A
PEG 54 DP 581460	PEG 56 DP 581460	ob108	359°45'55" C			20.00 C		Class A
PEG 56 DP 581460	PEG 33 DP 581460	ob111	359°45'55" C			20.00 C		Class A
PEG 53 DP 581460	DISK 55 DP 581460	ob106	359°50'00" C			15.00 C		Class A
DISK 55 DP 581460	UNMK 35 DP 581460	ob109	359°50'00" C			25.00 C		Class A
PEG 56 DP 581460	PEG 57 DP 581460	ob112	89°50'00" C			29.87 C		Class A
PEG 57 DP 581460	DISK 55 DP 581460	ob113	148°52'00" C			5.83 C		Class A
DISK 55 DP 581460	PEG 58 DP 581460	ob110	30°48'00" C			5.83 C		Class A
PEG 58 DP 581460	PEG 37 DP 581460	ob115	89°50'00" C			29.91 C		Class A
PEG 57 DP 581460	PEG 34 DP 581460	ob114	359°50'00" C			20.00 C		Class A
PEG 58 DP 581460	PEG 36 DP 581460	ob116	359°50'00" C			20.00 C		Class A
PEG 58 DP 581460	UNMK 68 DP 581460	ob117	179°50'00" C			20.00 C		Class A

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
UNMK 69 DP 581460	UNMK 70 DP 581460	ob144	89°49'45" C			55.84 C		Class A
UNMK 70 DP 581460	UNMK 68 DP 581460	ob145	359°50'00" C			6.00 C		Class A
UNMK 15 DP 581460	UNMK 64 DP 581460	ob49	269°04'00" C			44.03 C		Class A
UNMK 64 DP 581460	UNMK 65 DP 581460	ob138	273°04'00" C			27.23 C		Class A
UNMK 65 DP 581460	UNMK 66 DP 581460	ob139	269°56'00" C			17.98 C		Class A
UNMK 66 DP 581460	UNMK 63 DP 581460	ob140	179°56'00" C			137.03 C		Class A
UNMK 63 DP 581460	UNMK 67 DP 581460	ob137	179°56'00" C			201.19 C		Class A
IB 1 DP 500853	PEG 38 DP 581460	ob10	119°26'00" M			29.55 M		
IB 1 DP 500853	PEG 40 DP 581460	ob11	114°34'00" M			34.90 M		
IB 1 DP 500853	PEG 41 DP 581460	ob12	128°16'20" M			70.69 M		
IB 1 DP 500853	PEG 48 DP 581460	ob13	144°00'10" M			54.15 M		
IB 1 DP 500853	DISK 46 DP 581460	ob14	149°25'40" M			56.70 M		
IB 1 DP 500853	PEG 47 DP 581460	ob15	149°29'20" M			50.86 M		
IB 1 DP 500853	DISK 42 DP 581460	ob16	176°26'20" M			43.93 M		
IB 1 DP 500853	DISK 43 DP 581460	ob17	177°50'20" M			73.25 M		
IB 1 DP 500853	PEG 45 DP 581460	ob18	158°26'20" M			78.67 M		
IT 1 DP 360565	PEG 32 DP 581460	ob37	190°31'00" M			14.86 M		
IT 1 DP 360565	PEG 33 DP 581460	ob38	130°05'00" M			22.60 M		
IT 1 DP 360565	PEG 34 DP 581460	ob39	107°02'20" M			49.35 M		
IT 1 DP 360565	PEG 36 DP 581460	ob40	105°11'40" M			55.11 M		
IT 1 DP 360565	PEG 58 DP 581460	ob41	122°54'00" M			63.41 M		
IT 1 DP 360565	DISK 55 DP 581460	ob42	128°08'00" M			63.89 M		
IT 1 DP 360565	PEG 57 DP 581460	ob43	126°06'40" M			58.48 M		
IT 1 DP 360565	PEG 53 DP 581460	ob44	137°16'10" M			74.13 M		

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
IT 1 DP 360565	PEG 54 DP 581460	ob45	162°15'30" M			57.27 M		
IT 1 DP 360565	DISK 49 DP 581460	ob46	182°40'10" M			54.67 M		
IT 1 DP 360565	PEG 56 DP 581460	ob47	153°18'20" M			38.67 M		
IT III DP 11530	DISK 19 DP 581460	ob120	120°05'00" M			29.01 M		
IT III DP 11530	PEG 37 DP 581460	ob121	143°54'00" M			42.75 M		
IT III DP 11530	PEG 20 DP 581460	ob122	155°08'20" M			60.11 M		
IT I DP 581460	PEG J DP 322521	ob126	97°19'10" M			87.40 M		
IT I DP 581460	PEG B DP 500853	ob127	265°13'35" M			112.99 M		
IT I DP 581460	POST C DP 500853	ob128	264°12'15" M			115.66 M		
IT I DP 581460	DISK 50 DP 581460	ob129	174°56'00" M			11.40 M		
IT I DP 581460	PEG 51 DP 581460	ob130	177°40'00" M			26.38 M		
IT I DP 581460	PEG 52 DP 581460	ob131	209°29'00" M			30.33 M		
IT I DP 581460	DISK 8 DP 581460	ob132	232°44'00" M			18.83 M		
IT II DP 581460	IS 44 DP 581460	ob134	167°56'40" M			45.35 M		
IT II DP 581460	PEG 31 DP 581460	ob135	243°39'50" M			100.63 M		
SS 39 SO 11260	SS 40 SO 11260	ob118	269°49'45" M			239.86 M		

Mark Name	Mark Condition	Description
DISK 19 DP 581460		Peg (1) DP 10453 reinstated, set in conc at fce end
DISK 42 DP 581460		in fce railing
DISK 43 DP 581460		on top of wooden strainer
DISK 46 DP 581460		set in concrete
DISK 49 DP 581460		on top of wooden strainer
DISK 50 DP 581460		on top of fence stay
DISK 55 DP 581460		set in concrete
DISK 8 DP 581460		Peg F DP 500853 reinstated, Disk on top of wooden deer fce strainer
IB 1 DP 500853		d 0.2m 1m N of seal
IS 44 DP 581460		IS in tree root
IT 1 DP 360565		d 0.05m 1m N of seal

Mark and Vector

Survey Number DP 581460

Meridional Circuit Bluff 2000

Mark Name	Mark Condition	Description
IT I DP 581460		d 0.3m in grass
IT II DP 581460		d 0.05m in gravel, 9.5m W of fce
IT III DP 11530		d 0.3m under cover in seal
PEG 11 DP 581460		Peg A DP 502767 reinstated
PEG 20 DP 581460		Peg (2) DP 10453 reinstated, on W side of 50 yr conc strainer post
PEG 31 DP 581460		in 30 yr wooden post and wire deer fce
PEG A DP 500853		flush in gravel
PEG B DP 500853		OP on SW side of new wooden strainer post
PEG B DP 502767		OP 0.2m SE of strainer post
PEG C DP 502767		OP 0.15m SW of wooden deer fce strainer
PEG E DP 500853		0.15 NW of strainer post
PEG J DP 322521		0.7m E & 0.15m N fce int
POST C DP 500853		Large wooden strainer post
SS 39 SO 11260		d 0.3m under cover in seal
SS 40 SO 11260		d 0.3m under cover in grass 1.5m N of seal

***** End of Report *****

EASEMENT SCHEDULE – DP 581460

Lots 1 – 13 & 100 being a Subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.

MEMORANDUM OF EASEMENTS			
Purpose	Shown	Servient Tenement (Burdened Land)	Dominant Tenement (Benefited Land)
Right of Way, Right to drain Water & Sewage, Right to convey Water, Electricity & Telecommunications.	(A)	Lot 100 hereon	Lots 5 and 10 - 13 hereon
	(B)	Lot 3 hereon	Lots 1, 2 & 4 hereon
	(C)	Lot 4 hereon	Lots 1 - 3 hereon
	(D)	Lot 8 hereon	Lots 6, 7 & 9 hereon
	(E)	Lot 9 hereon	Lots 6 - 8 hereon
Right to drain Water	(A)	Lot 100 hereon	Lots 5 - 9 hereon
	(I)	Lot 11 hereon	Lots 5 - 9 hereon
	(J)	Lot 9 hereon	Lots 6 - 8 hereon
MEMORANDUM OF EASEMENTS IN GROSS			
Purpose	Shown	Servient Tenement (Burdened Land)	Grantee
Right to drain Water	(G)	Lot 10 hereon	Southland District Council
	(H)	Lot 12 hereon	
	(B)	Lot 3 hereon	
	(F)		
Right to convey Telecommunications	(B)	Lot 3 hereon	Chorus New Zealand Ltd
	(C)	Lot 4 hereon	
	(D)	Lot 8 hereon	
	(E)	Lot 9 hereon	

AMALGAMATION SCHEDULE – DP 581460


Lots 1 – 13 & 100 being a Subdivision of Lots 17A, 18 & 18A DP 80
and Lot 1 DP 502767.

AMALGAMATION CONDITION

That Lot 100 hereon and Lot 12 hereon be held in the same Record of Title.


CSN 1689413.

OCCUPATION DIAGRAM



13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.

Surveyor: Merryn Kay Maguire
 Firm: Bonisch Consultants Ltd






Surveyor: Merryn Kay Maguire
Firm: Bonisch Consultants Ltd
Date of Survey: 22/08/2022




Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.

Record of Survey
DP 581460


Digitally Generated Plan
Generated on: 05/01/2023 1:33pm Page 14 of 22

Deposited on: 1/12/2022





Land District: Southland	Record of Survey DP 581460	S 4/5
Digitally Generated Plan Generated on: 05/01/2023 1:33pm Page 16 of 22	Surveyor: Meryn Kay Maguire Firm: Bonisch Consultants Ltd Date of Survey: 22/08/2022	Deposited on: 1/12/2022



Land District: Southland	Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.	Record of Survey DP 581460	Deposited on: 1/12/2022
Digitally Generated Plan Generated on: 05/01/2023 1:33pm Page 17 of 22	Surveyor: Meryn Kay Maguire Firm: Bonisch Consultants Ltd Date of Survey: 22/08/2022		



Land District: Southland

Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.


Surveyor: Merryn Kay Maguire
Firm: Bonisch Consultants Ltd
Date of Survey: 22/08/2022

Record of Survey
DP 581460

Digitally Generated Plan
Generated on: 05/01/2023 1:33pm Page 18 of 22



Dejoux Road



T 2/5

Land District: Southland


Digitally Generated Plan

Generated on: 05/01/2023 1:33pm Page 19 of 22

Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.

Surveyor: Meryn Kay Maguire
Firm: Bonisch Consultants Ltd
Date of Survey: 22/08/2022


Record of Survey
DP 581460
Deposited on: 1/12/2022





Diag. AD

Dejoux Road



T 4/5

Land District: Southland

Digitally Generated Plan

Generated on: 05/01/2023 1:33pm Page 21 of 22

Lots 1 - 13 & 100 being a subdivision of Lots 17A, 18 & 18A DP 80 and Lot 1 DP 502767.

Surveyor: Meryn Kay Maguire
Firm: Bonisch Consultants Ltd
Date of Survey: 22/08/2022

Record of Survey
DP 581460

Deposited on: 1/12/2022

