

Record of Survey - SO 583291

Survey Number SO 583291
Surveyor Reference 6897 - 24 Te Mete Road, Te Puna
Surveyor Richard Stuart Abbott
Survey Firm Survey Worx Ltd
Surveyor Declaration I Richard Stuart Abbott, being a licensed cadastral surveyor, certify that--
 (a) this dataset provided by me and its related survey are accurate, correct and in accordance with the Cadastral Survey Act 2002 and Cadastral Survey Rules 2021; and
 (b) the survey was undertaken by me or under my personal direction.
 Declared on 26 Oct 2022 04:01 PM

Survey Details

Dataset Description Boundary Reinstatement of Part Alloment 208A1B Parish of Te Puna Block ML 568644
Purpose Simple Boundary Reinstatement
Status Registered **Type** Survey
Land District South Auckland **Survey Class** Class A
Meridional Circuit Bay of Plenty 2000 **Vertical Datum** None

Survey Dates

Surveyed Date 04/10/2022 **Certified Date** 26/10/2022
Submitted Date 26/10/2022 16:01:15 **Survey Approval Date** 27/10/2022
Deposit Date

Referenced Surveys

Survey Number	Land District	Bearing Correction
DPS 56608	South Auckland	0°00'00"
SO 59678	South Auckland	0°00'00"
DPS 65547	South Auckland	0°00'00"
ML 19422	South Auckland	0°00'00"
DP 333957	South Auckland	0°00'00"
DP 426862	South Auckland	0°00'00"
DP 450362	South Auckland	0°00'00"
DP 574682	South Auckland	0°00'00"
DPS 90184	South Auckland	0°00'00"

Territorial Authorities

Western Bay of Plenty District

Comprised In

RT 1033461

Mark and Vector

Survey Number SO 583291

Meridional Circuit Bay of Plenty 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
IS XVI ML 19422	IT XVIII ML 19422	ob0	24°03'45" M			92.37 M		
IS XVI ML 19422	IB CAM DP 426862	ob1	177°36'49" M			558.63 M		
IS XVI ML 19422	IB 3 DP 409003	ob2	171°41'10" M			523.16 M		
IS XVI ML 19422	IB 1 DP 574682	ob3	190°41'25" M			622.36 M		
IB 1 DP 574682	IS XII DPS 56608	ob10	85°09'40" A	DP 574682	0°00'00"	71.79 A	DP 574682	
IS XII DPS 56608	IS V SO 59678	ob12	19°55'30" A	SO 59678	0°00'00"	53.96 A	SO 59678	
IS V SO 59678	IS II DPS 56608	ob13	359°42'30" A	DPS 90184	0°00'00"	86.79 A	DPS 90184	
IS II DPS 56608	IB 5 DP 426862	ob14	130°54'30" A	DP 426862	0°00'00"	42.20 A	DP 426862	
IB 5 DP 426862	IB CAM DP 426862	ob15	164°30'20" A	DP 426862	0°00'00"	64.87 A	DP 426862	
IB CAM DP 426862	IB 3 DP 409003	ob9	52°18'00" A	DP 450362	0°00'00"	66.21 A	DP 450362	
IB 1 DP 574682	IS XIII DPS 56608	ob11	222°25'30" A	DP 574682	0°00'00"	34.43 A	DP 574682	
IS XIII DPS 56608	IB XII DPS 66093	ob16	303°22'40" A	DP 333957	0°00'00"	140.24 A	DP 333957	
IB XII DPS 66093	IT VI ML 19422	ob17	328°14'50" A	DP 333957	0°00'00"	151.54 A	DP 333957	
IT VI ML 19422	IS V ML 19422	ob18	29°26'30" A	ML 19422	0°00'00"	157.50 A	ML 19422	
IS V ML 19422	IS IV ML 19422	ob19	29°26'30" A	ML 19422	0°00'00"	153.13 A	ML 19422	
IS IV ML 19422	IS XV ML 19422	ob21	83°35'40" A	ML 19422	0°00'00"	117.83 A	ML 19422	
IS XV ML 19422	IS XVI ML 19422	ob22	24°03'45" A	ML 19422	0°00'00"	161.30 A	ML 19422	
IS V ML 19422	PEG 16 SO 583291	ob20	47°09'00" A	ML 19422	0°00'00"	12.89 A	ML 19422	
PEG 16 SO 583291	PEG 17 SO 583291	ob23	25°15'40" R	ML 19422	0°00'00"	353.66 R	DPS 65547	Class A
PEG 17 SO 583291	PEG 18 SO 583291	ob24	114°44'00" R	DPS 65547	0°00'00"	80.10 R	DPS 65547	Class A
PEG 18 SO 583291	PEG 19 SO 583291	ob25	205°17'00" R	ML 19422	0°00'00"	0.37 R	DPS 65547	Class A
PEG 19 SO 583291	PEG 20 SO 583291	ob26	112°17'00" R	ML 19422	0°00'00"	12.21 R	ML 19422	Class A
PEG 20 SO 583291	IS XVI ML 19422	ob27	75°12'00" M			14.34 M		
IS XVI ML 19422	PEG 19 SO 583291	ob4	272°12'00" M			25.18 M		
IS XVI ML 19422	PEG 18 SO 583291	ob5	272°59'00" M			25.04 M		
IS XVI ML 19422	PEG 17 SO 583291	ob6	289°35'40" M			103.76 M		

Mark and Vector


Survey Number SO 583291



Meridional Circuit Bay of Plenty 2000

From	To	Code	Bearing	Adpt Surv	Bearing Correction	Distance	Adpt Surv	Class
IS XVI ML 19422	PEG 16 SO 583291	ob7	221°06'10" M			378.26 M		
IS XVI ML 19422	IS XXX ML 19422	ob8	29°43'00" M			15.84 M		

*** End of Report ***

Occupation Diagram





S 1/2		Record of Survey SO 583291 Approved on: 27/10/2022	
Boundary Reinstatement of Part Allotment 208A1B Parish of Te Puna Block ML 568644		Surveyor: Richard Stuart Abbott Firm: Survey Worx Ltd Date of Survey: 4/10/2022	
Land District: South Auckland	Digitally Generated Plan Generated on: 27/10/2022 06:27am Page 5 of 6		



Diag. B


Lot 1 DPS 4196

Lot 5 DPS 79817

Te Mete Road

Part Allotment 208A1B
Parish of Te Puna
Block ML 568644

Allot 208A2B1
Te Puna PSH



S 2/2

Land District: South Auckland

Digitally Generated Plan

Generated on: 27/10/2022 06:27am Page 6 of 6

Boundary Reinstatement of Part Allotment 208A1B Parish of Te Puna Block ML 568644

Surveyor: Richard Stuart Abbott
Firm: Survey Worx Ltd
Date of Survey: 4/10/2022

Record of Survey
SO 583291
Approved on: 27/10/2022